

Supplemental Type Certificate

Number SA3334WE

This Certificate issued to AIR MEDIC, L.L.C.
7309 Clybourne Avenue, Unit 3
Sun Valley, California 91352

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product Type Certificate Number : A16WE
Make : The Boeing Company
Model : 737-100, -200, -300, -400, -500 Series

Description of Type Design

Change: Installation of Stretcher Carrier, in accordance with FAA Sealed Air Medic Stretcher Carrier Master Drawing List AM-2001, Revision "Z", dated August 12, 1988, or later FAA approved revision, and utilization in accordance with Air Medic Operations Specifications AM 2017, is required as part of this installation.

Limitations and Conditions: The approval of this change in type design applies basically to the Boeing 737-100, -200, -300, -400, -500 Series only. This approval should not be extended to other aircraft of this model on which other previously approved modifications are incorporated unless it is determined by the installer that the interrelationship between the change and those other previously approved modifications will introduce no adverse effect upon the airworthiness of that aircraft. This determination should include consideration of significant changes in weight distribution such as an increase in the fixed disposable weight in the fuselage.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : November 15, 1976

Date of issuance : February 8, 1977

Date reissued:

Date amended : April 28, 1989, January 14, 1993,
August 21, 2003



By direction of the Administrator

(Signature)

Program Manager, Systems and Equipment Branch
Los Angeles Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.