Department of Transportation - Federal Abiation Administration

## Supplemental Type Certificate

Number SA3623WE

This Certificate issued to

AIR MEDIC, L.L.C. 7309 Clybourne Avenue, Unit 3 Sun Valley, California 91352

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airmorthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product Type Certificate Number :

A6WE

**McDonnell Douglas Corporation** 

Mordel .

DC-9-11, DC-9-12, DC-9-13, DC-9-14, DC-9-15, DC-9-21, DC-9-31, DC-9-32, DC-9-34, DC-9-41, DC-9-51, DC-9-81,

DC-9-82, DC-9-83, DC-9-87, MD-88, MD-90-30, 717-200

Description of Type Design Change: Installation of Stretcher Carrier in accordance with FAA Approved Master Drawing List AM-2001, Revision "M" dated 4-3-78, or later FAA approved revision and utilized in accordance with Air Medic Operations Specification AM 2017.

Similations and Conditions: This installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this change and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. This determination should include consideration of significant changes in weight distribution, such as increase in the fixed disposable weight in the fuselage. A copy of this STC must be included in the permanent records of the modified aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: November 15, 1976

Date of issuance: April 13, 1978

Late reissued:

Late amended: October 19, 1995, July 17, 2003

MINISTRE

Program Manager, Systems and Equipment Branch Los Angeles Aircraft Certification Office

(Title)

(Signature)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.